DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

Printed: 07/25/2013 FORM APPROVED OMB NO. 0938-0391

NAME OF PROVIDER OR SUPPLIER CHRISTIAN HEALTH CARE CENTER SEGARON DRIVE LYNDEN, WA 98254 MANUAL PROVIDER OF SUPPLIER CHRISTIAN HEALTH CARE CENTER SUMMARY STATEMENT OF DEFICIENCE SOLD STRUCK LYNDEN, WA 98254 MANUAL PROVIDER OF SUMMARY STATEMENT OF DEFICIENCE SOLD STRUCK LYNDEN, WA 98254 MANUAL PROVIDER OF SUMMARY STATEMENT OF DEFICIENCE STRUCK LYNDEN, WA 98254 MANUAL PROVIDER OF SUMMARY STATEMENT OF DEFICIENCE STRUCK LYNDEN, WA 98254 K 000	AND PLAN OF CORRECTION IDENTIFICA		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01		(X3) DATE SURVEY COMPLETED	
CHRISTIAN HEALTH CARE CENTER (A4) ID PREFIX (RACH DEPRICIENCY MLST SEE PRIECLED BY FULL PREFIX (RACH DEPRICIENCY MLST SEE PRIECLED BY FULL PREFIX (RACH DEPRICIENCY MLST SEE PRIECLED BY FULL PREFIX (RACH CORNECTIVE ACTION SHOULD BE CHOSS-REFERENCED TO THE APPROPRIATE DEPRIENCY) K 000 INITIAL COMMENTS An unannounced Life Safety Code Survey was conducted at Christian Health Care Center. Lynden, Washington, on July 25, 2013 by staff from the Washington State Partol, Fire Protection Bureau, Oak Harbor Detachment. The 2000 existing edition of the Life Safety Code was utilized for the survey in accordance to 42 CFR 483.70: Requirements for Long Term Care The LTC 142 bed facility with a census of 125, consisted of a Type V-113, 1 story structure, built in 2000 which has no basement The facility is fully sprinkled with an automatic fire alarm system in place. Exit discharge points are to grade and have an all weather surface and lead to a public way. A Federal Life Safety Survey was conducted July 25, 2013. The Administrator as well as members of the Maintenance Staff accompanied the Deputy State Fire Marshal throughout the facility tour and paperwork verification from 9:30 AM to 1:00 PM. While conducting the survey on July 25, 2013, no federal deficiencies were found. The facility is in compliance with the Life Safety Code 2000 Edition as adopted by C.M.S. Deputy State Fire Marshal Deputy State Fire Marshal			505406	i	B. WING		07/25/2013	
PREFIX REGULATORY OR LSC IDENTIFYING INFORMATION) K 000 INITIAL COMMENTS An unannounced Life Safety Code Survey was conducted at Christian Health Care Center. Lynden, Washington, on July 25, 2013 by staff from the Washington State Patrol, Fire Protection Bureau, Oak Harbor Detachment. The 2000 existing edition of the Life Safety Code was utilized for the survey in accordance to 42 CFR 483.70. Requirements for Long Term Care The LTC 142 bed facility with a census of 125, consisted of a Type V-111, 1 story structure, built in 2000 which has no basement. The facility is fully sprinkled with an automatic fire alarm system in place. Exit discharge points are to grade and have an all weather surface and lead to a public way. A Federal Life Safety Survey was conducted July 25, 2013. The Administrator as well as members of the Maintenance Staff accompanied the Deputy State Fire Marshal throughout the facility tour and paperwork verification from 9:30 AMI to 1:00 PM. While conducting the survey on July 25, 2013, no federal deficiencies were found. The facility is in compliance with the Life Safety Code 2000 Edition as adopted by C.M.S. Deputy State Fire Marshal				855 AARON DRIVE				
An unannounced Life Safety Code Survey was conducted at Christian Health Care Center, Lynden, Washington, on July 25, 2013 by staff from the Washington State Patrol, Fire Protection Bureau, Oak Harbor Detachment. The 2000 existing edition of the Life Safety Code was utilized for the survey in accordance to 42 CFR 483.70. Requirements for Long Term Care. The LTC 142 bed facility with a census of 125, consisted of a Type V-111, 1 story structure, built in 2000 which has no basement. The facility is fully sprinkled with an automatic fire alarm system in place. Exit discharge points are to grade and have an all weather surface and lead to a public way. A Federal Life Safety Survey was conducted July 25, 2013. The Administrator as well as members of the Maintenance Staff accompanied the Deputy State Fire Marshal throughout the facility bour and paperwork verification from 9:30 AM to 1:00 PM. While conducting the survey on July 25, 2013, no federal deficiencies were found. The facility is in compliance with the Life Safety Code 2000 Edition as adopted by C M.S.	PRÉFIX	(EACH DEFICIENC	Y FULL	PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE		COMPLETION	
Lynden, Washington, on July 25, 2013 by staff from the Washington State Patrol, Fire Protection Bureau, Oak Harbor Detachment. The 2000 existing edition of the Life Safety Code was utilized for the survey in accordance to 42 CFR 483.70: Requirements for Long Term Care. The LTC 142 bed facility with a census of 125, consisted of a Type V-111, 1 story structure, built in 2000 which has no basement. The facility is fully sprinkled with an automatic fire alarm system in place. Exit discharge points are to grade and have an all weather surface and lead to a public way. A Federal Life Safety Survey was conducted July 25, 2013. The Administrator as well as members of the Maintenance Staff accompanied the Deputy State Fire Marshal throughout the facility tour and paperwork verification from 9:30 AM to 1:00 PM. While conducting the survey on July 25, 2013, no federal deficiencies were found. The facility is in compliance with the Life Safety Code 2000 Edition as adopted by C.M.S. Deputy State Fire Marshal	K 000				K 000			
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE TITLE (X6) DATE		conducted at Christian Health Care Center, Lynden, Washington, on July 25, 2013 by staff from the Washington State Patrol, Fire Protection Bureau, Oak Harbor Detachment. The 2000 existing edition of the Life Safety Code was utilized for the survey in accordance to 42 CFR 483.70: Requirements for Long Term Care. The LTC 142 bed facility with a census of 125, consisted of a Type V-111, 1 story structure, built in 2000 which has no basement. The facility is fully sprinkled with an automatic fire alarm system in place. Exit discharge points are to grade and have an all weather surface and lead to a public way. A Federal Life Safety Survey was conducted July 25, 2013. The Administrator as well as members of the Maintenance Staff accompanied the Deputy State Fire Marshal throughout the facility tour and paperwork verification from 9:30 AM to 1:00 PM. While conducting the survey on July 25, 2013, no federal deficiencies were found. The facility is in compliance with the Life Safety Code 2000 Edition as adopted by C.M.S.						
LABOURD DU LUR TUNGEN CONTROL DE LE LA	Lancatto	NV DIDECTORS OF THE	AD-Park					

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.